Tintley Street - Balcony Views 13th January 2022 - The Col

enies St

N17JQ +44 (0)20 7566 7440 info@morrisand.company www.morrisand.company Street Balcon

+ Company Ltd.

24

mA



# 1–9 Huntley Street - Balcony Views Introduction

As part of an ongoing consultation process, Morris+Company is investigating the potential impact of proposal on neighbouring buildings. This document focuses on the rear facade of 1–9 Huntley Street, a residential building adjacent to the North Crescent site.

On 2nd December 2021 Morris+Company was granted access to a number of the flats within this building to photograph the residents' views of the site. From these photographs we have superimposed the relative perspective of the proposed massing to give an indication of its visual impact.



Aerial view of North Crescent



 $(\top)$ 

# **1–9 Huntley Street - Balcony Views** Scope of Study


The flats at 1–9 Huntley Street from which Morris+ Company were able to take photographs are:

1 Flat 4 (upper ground level)

2 Flat 5 (first floor level)

3 Flat 7 (second floor level)

All balconies accessed adjoin bedrooms.




Aerial view of North Crescent



 $(\top)$ 

# **1–9 Huntley Street - Balcony Views** Flat 4 (upper ground level)

View of existing




View of existing with proposal outlined





B

A



### **Material Palette**





#### Above Datum B Aluminium panels

Anodised perforated and solid aluminium panels

### Above Datum A New brickwork

New brickwork to match existing



# Below Datum A Existing brickwork


Brickwork cleaned and repaired where required



Datum A Datum B

# **1–9 Huntley Street - Balcony Views** Flat 5 (first floor level)


View of existing



View of existing with proposal outlined







### **Material Palette**



B

A



#### Above Datum B Aluminium panels

Anodised perforated and solid aluminium panels

### Above Datum A New brickwork

New brickwork to match existing



# Below Datum A Existing brickwork

Brickwork cleaned and repaired where required



Datum A Datum B


# **1–9 Huntley Street - Balcony Views** Flat 7 (second floor level)


View of existing



View of existing with proposal outlined

## View key





## **Material Palette**





#### Above Datum B Aluminium panels

Anodised perforated and solid aluminium panels

### Above Datum A New brickwork

New brickwork to match existing



Below Datum A Existing brickwork Brickwork cleaned and

repaired where required

.... A

Datum A Datum B

6 of 6