



IMAGE PROVIDED FOR
NEIGHBOURING FACADES
AND GENERAL CONTEXT

47 THEOBALDS ROAD
NOTE - IMAGE SHOWS PREVIOUS CONDITION BEFORE
2020 RENOVATION WORKS



IMAGE PROVIDED FOR
NEIGHBOURING FACADES
AND GENERAL CONTEXT

47 THEOBALDS ROAD
NOTE - IMAGE SHOWS PREVIOUS CONDITION BEFORE
2020 RENOVATION WORKS



IMAGE PROVIDED FOR
NEIGHBOURING FACADES
AND GENERAL CONTEXT

47 THEOBALDS ROAD
NOTE - IMAGE SHOWS PREVIOUS CONDITION BEFORE
2020 RENOVATION WORKS



47 THEOBALDS ROAD

CURRENT REAR ELEVATION
FOLLOWING RENOVATION 2020

PROPOSED LOCATION
OF CONDENSER UNIT -
LOCATED ON FLAT ROOF



47 THEOBALDS ROAD

CURRENT REAR ELEVATION
FOLLOWING RENOVATION 2020

PROPOSED LOCATION
OF CONDENSER UNIT -
LOCATED ON FLAT ROOF



IMAGE OF ADJACENT ROOFS
TO PROPERTIES TO EAST OF SITE