

[illegible]

NB: Information given is supplementary to the 4SC report and does not form part of the 4SC certification

Daily Inspection/Checks:

Hygiene unit clean and connected to services	Yes	Enclosure asbestos warning signs	Yes
Transit route sealed off and signed	Yes	Respirator areas warning signs	Yes
Waste/Skip area locked	Yes	Enclosure seals checked and intact	Yes
Warning labels attached to skip	Yes	Adequate negative pressure	Yes
Copy of METHOD STATEMENT read	Yes	NPU vented outside building	Yes
Operatives transiting in accordance with HSG247			Yes
Regular inspection of all areas (enclosure, transit route, surroundings, skip)			Yes
Were any defects/problems brought to attention of contractor?			N/A
All bagged asbestos locked in waste skip at end of shift if applicable			Yes
Site in clean, safe & tidy condition at end of shift			Yes

Analyst PDH WILLCOCK Signature Date 19-Aug-2014

Life Environmental Services

The natural choice for environmental compliance and risk management solutions

Head Office
4 Duckett's Wharf
South Street
Bishop's Stortford
CM23 3AR

Tel: 01279 503117
Fax: 01279 503162

New Meltham House
Units 37/38 Beresford Way
Chesterfield
S41 9FG
Tel: 01246 263 370
Fax: 01246 283 399



CERTIFICATE OF REOCCUPATION
 Project No. B-45739 Shift No. 1 Enclosure Reference No. Garage

Name and address of client		E Brit Services, Charfleets Industrial Estate, Kings Road, Canvey Island. Essex SS8 0QY.			
Site Address		13-15 John Mews, London.WC1N 2PA.			
Description of works/Areas to be assessed		Removal of AIB Cladding to Steelwork within the garage.			
Name of asbestos removal contractor		E Brit Services.			
Has the LARC site supervisor confirmed that their inspection of the enclosure is completed and satisfactory (Representative to sign below)		Yes	Analyst not to proceed without contractor's confirmation of a satisfactory inspection.		
CONTRACTOR'S REPRESENTATIVE CONFIRMATION OF ENCLOSURE INSPECTION					
I confirm that the enclosure has been inspected and is satisfactory for the analyst to proceed with stage 1 of the reoccupation procedure					
Name: C Brackett		Signature:		Time: 13:00	Date: 19-Aug-2014
Stage 1 of 4: Preliminary check of site condition and job completeness					
1.1 Plan of work checked to confirm areas to be assessed and entire defined work area agreed and completed : (record any problems, differences or known asbestos to remain)					
Are the following intact and operating?	1.2 Work areas intact	1.3 Enclosure intact	1.4 NPU/Vac Operational	1.5 Hygiene Unit Operational	1.6 Vision Panel/ CCTV present
	Yes	Yes	Yes	Yes	Yes
Inspections with viewing panel / cctv	Adequate Lighting	Yes	Suitable sufficient Access Equipment	Yes	
Areas free from obvious asbestos waste & debris	1.7 Enclosure and Surrounding area		1.8 Waste route/skip		1.9 Transit route/Hygiene Unit
	Yes		Yes		Yes
Stage 1: Pass (STRIKE THROUGH REST OF FORM IF FAILED)					
Comments: As the site is undergoing major re-furbishment surrounding area and waste/transit have general debris present.					
Assessed by name: PDH Willcock		Signature:		Time: 13:06	Date: 19-Aug-14
Stage 2 of 4: Thorough visual inspection					
2.1 Airlock/baglock and enclosure are free from waste bags, materials and unnecessary equipment	Yes	2.4 Any evidence of lock down sprays (E.g. PVA) where the LARC was not instructed to			No
2.2 The enclosure and airlocks have been visually inspected and within limits of accessibility have been deemed to be visibly clean of dust and debris	Yes	2.5 ACM's removed, encapsulated or enclosed as specified in the plan of works			Yes
2.3 Enclosure is dry	Yes	2.6 Any remaining asbestos has been left in good condition or encapsulated depending on the material and has been marked on the attached plan			N/A

Life Environmental Services

The natural choice for environmental compliance and risk management solutions

Issue 5/COR/Life/Jan14

Head Office
 4 Duckett's Wharf
 South Street
 Bishop's Stortford
 CM23 3AR
 Tel: 01279 503117
 Fax: 01279 503162

 New Meltham House
 Units 37/38 Beresford Way
 Chesterfield
 S41 9FG Tel: 01246
 263 370
 Fax: 01246 283 399


0610

CERTIFICATE OF REOCCUPATION
 Project No. B-45739 Shift No. 1 Enclosure Reference No. Garage

Stage 2: Pass (STRIKE THROUGH REST OF FORM IF FAILED) The length of the visual was <u>16</u> mins Comments:					
Assessed by name: PDH Willcock Signature: Time: 13:37 Date: 19-Aug-2014					
Stage 3 of 4: Clearance air testing inside the enclosure					
3.1 All areas dry	Yes	3.2 Volume/Area of enclosure	15m2/45m3	3.3 Method of disturbance	Brushing
3.4 NPU's off & capped	Yes	3.5 Number of samples	2	3.6 Duration of disturbance	3 minutes
Air test certificate No's: AMC-01					
Stage 3: Pass (STRIKE THROUGH REST OF FORM IF FAILED) The enclosure can be dismantled Comments:					
Assessed by name: PDH Willcock Signature: Time: 15:06 Date: 19-Aug-2014					
Stage 4 of 4: Assessment of site for reoccupation (after the enclosure is removed)					
4.1 Former enclosure and equipment has been dismantled and the work area and immediate surroundings are visibly free from any asbestos debris, enclosure materials and waste?	Yes	4.2 Transit / waste route and area is free from any visible asbestos debris, enclosure materials and waste?	Yes		
		4.3 Was there any evidence of debris and dust being released from the enclosure dismantlement?	No		
4.4 Any known ACMS within work area or any uncovered during stage 4 are left in a safe condition?	N/A	4.4 Reassurance Air testing conducted: If no reassurance test was required give reasons why below	Yes		
Comments: Reassurance test satisfactory <0.01f/ml.					
Stage 4: Pass The area Can be re-occupied Assessed by name: PDH Willcock Signature: Time: 15:59 Date: 19-Aug-2014					
Contractor's representative acknowledgement: I have been advised by Paul Willcock of Life Environmental that the Certificate of Reoccupation has been issued because the area has Passed All Stages in accordance with HSG 248 The analyst's guide for sampling, analysis and clearance procedures.					
Contractor representative name: C Brackett Signature: Time: 16:01 Date: 19-Aug-2014					





Name and address of client	E Brit Services Charfleets Industrial Estate, Kings Road, Canvey Island. Essex. SS8 0QY.
Site address	13-15 John Mews London WC1N 2PA.
Areas to be assessed and brief description of job	Removal of AIB Cladding to steelwork in the garage.
Name of asbestos removal contractor	E Brit Services.

[illegible]

- 1 Life Environmental is accredited by UKAS (number 6150) for sampling and fibre counting for asbestos in air. This is carried out in accordance with HSG248 and documented in house methods.
2 This certificate should not be taken as an indication of the suitability of an area for reoccupiation following asbestos removal unless accompanied by a Life Environmental certification of reoccupiation report.
3 The results are recorded as being less than the limit of detection for the volume of air sampled e.g. for 480 ltr sample the result is recorded as being <0.01/ml for 480 ltr sample the result is recorded.
4 The Calculated Result is the actual fibre concentration reported as per Section 5.3.1 in HSG248 The Analyist Guide. The reported result will be in line with the relevant Limit Of Detection/Control limit

KEY: CM = Compliance Monitoring; L = Leak; B = Background; CL = Clearance Testing; R = Reassurance; FB = Field Blank MNC = Mounted Not Counted

Microscope No.	MS11MB	Graticule Diameter (um)	100
Flow Meter No.	F7 F60	HSE/NPL Test Slide No.	NPL12
Where counted?	Site	5th Band Observed on Test Slide	Yes
Watch/Thermometer/Barometer No.	W35		
Stage Micrometer No.	MA27	"O" Ring Diameter (mm)	21.7

Date 19-Aug-2014

New Meltham House
Units 37/38 Beresford Way
Chesterfield
S41 9FG
Tel: 01246 263 370
Fax: 01246 283 399



Life Environmental Services
The natural choice for environmental
compliance and risk management solutions

Issue 6/Air Test/Life/Jan14

Page of

PLAN OF WORK AREA




Project No. B-45739 Shift No. 1

Report No. AMC-01

Name and address of client	E-Brit Services, Charfleets Industrail Estate, Kings Road, Canvey Island, Essex.SS8 0QY.
Site address	13-15 John Mews, London WC1N 2PA.
Areas to be assessed and brief description of the works	Removal of AIB Cladding to steelwork within the garage.

Dimensions of
the enclosure/s :
H: 3ms
L: 3ms
W: 5ms



Name PDH Willcock Signature [Signature] Date 19-Aug-2014

Contractor's Name C Brackett Signature [Signature] Company E -Brit Services Ltd.