

lmage_001

Existing Side Elevation (Rudgewick Terrace)



Image_002

Existing Front Elevation



Image_003

Existing Side Elevation (Ramp Access)



Image_004

Existing Rear Elevation



lmage_005

Neighbouring building with large format glazing



lmage_006

The surrounding context of 22 Avenue Road



lmage_007

The surrounding buildings opposite the site



Image_008

Main entrance

Currently no step-free access to or from the building.



Image_009

Access

Pedestrian step access and ramp access to underground car park



Image_010

Proposed step-free access

By removing part of the low brick wall there can be access from the existing ramp to or from the building.



lmage_011

View from main entrance

Currently no step-free access to or from the building.

Existing window condition

Existing wooden windows in dilapidated condition, which require replacing.







Image_013







Image_015



Image_016