



NOTE:
 This survey is of a preliminary nature. The trees were inspected from the ground only and no decay detection equipment was employed. The survey does not cover the arrangements that may be required in connection with the laying or removal of underground services.
 Branch spread in metres is taken at the four cardinal points to derive an accurate representation of the crown.
 Root Protection Areas (RPA) are derived from stem diameter measured at 1.5 m above adjacent ground level (taken on sloping ground on the upslope side of the tree base).

Landmark Trees
 Hidden House, 4th Floor, 57 Rathbone Place, London W1T 4JU
 Tel: 0207 691 4544 Mobile: 07812 269928
 Email: info@landmarktrees.co.uk Web: www.landmarktrees.co.uk

Drawing Title: Tree Constraints Plan
 1:200@ A1
 September 2021

Key:	Category	Category
● High Quality	Category A	Crown Spread
● Medium Quality	Category B	Alternate RPA
● Low Quality	Category C	Tree Number
● Category U	Category U	Species
● Trees Unsuitable for Retention		Category
		Tree Position Approximate (not shown on original survey)