


TREE SURVEY SITE PLAN & SUMMARY PHOTOGRAPHS
10 St Mark's Crescent, London, NW1 7TS



Tree T1 viewed to north east from front of property



T1 sitting within limited 300mm width raised retainer



Cracking to front boundary wall and raised retainer due to limited rooting environment