

Confidential

1 Wadham Gardens,
London, NW3 3DN

Basement Impact Assessment
Audit

For

London Borough of Camden

Project Number:

13693-34

May 2022

Campbell Reith Hill LLP
15 Bermondsey Square
London
SE1 3UN

T: +44 (0)20 7340 1700
E: london@campbellreith.com
W: www.campbellreith.com

Document History and Status

Revision	Date	Purpose/Status	File Ref	Author	Check	Review
D1	March 2022	Comment	AAgk-13693-34-070322-1 Wadham Gardens-D1.docx	AA	GK	GK
F1	May 2022	Final	AAgk-13693-34-190522-1 Wadham Gardens-F1.docx	AA	GK	GK

This document has been prepared in accordance with the scope of Campbell Reith Hill LLP's (CampbellReith) appointment with its client and is subject to the terms of the appointment. It is addressed to and for the sole use and reliance of CampbellReith's client. CampbellReith accepts no liability for any use of this document other than by its client and only for the purposes, stated in the document, for which it was prepared and provided. No person other than the client may copy (in whole or in part) use or rely on the contents of this document, without the prior written permission of Campbell Reith Hill LLP. Any advice, opinions, or recommendations within this document should be read and relied upon only in the context of the document as a whole. The contents of this document are not to be construed as providing legal, business or tax advice or opinion.

© Campbell Reith Hill LLP 2022

Document Details

Last saved	19/05/2022 12:35
Path	AAgk-13693-34-190522-1 Wadham Gardens-F1.docx
Author	Ansaff Ashraff, B.Eng
Project Partner	E M Brown, BSc MSc CGeol FGS
Project Number	13398-34
Project Name	1 Wadham Gardens, NW3 3DN
Planning Reference	2021/6174/P

Contents

1.0 Non-technical summary 1

2.0 Introduction 2

3.0 Basement Impact Assessment Audit Check List..... 4

4.0 Discussion 8

5.0 Conclusions10

Appendices

- Appendix 1: Consultation Responses
- Appendix 2: Audit Query Tracker
- Appendix 3: Supplementary Supporting Documents

1.0 NON-TECHNICAL SUMMARY

- 1.1. CampbellReith was instructed by the London Borough of Camden, (LBC) to carry out an audit on the Basement Impact Assessment submitted as part of the Planning Submission documentation for 1 Wadham Gardens, London, NW3 3DN (planning reference 2021/6174/P). The basement is considered to fall within Category B as defined by the Terms of Reference.
- 1.2. The Audit reviewed the Basement Impact Assessment for potential impact on land stability and local ground and surface water conditions arising from basement development in accordance with LBC's policies and technical procedures.
- 1.3. CampbellReith was able to access LBC's Planning Portal and gain access to the latest revision of submitted documentation and reviewed it against an agreed audit check list.
- 1.4. The BIA has been prepared by Quadrant Harmon Consulting Engineers and Geo-Environmental Services Ltd. In the updated submissions, the authors have demonstrated they hold the required qualifications as per CPG: Basements.
- 1.5. The proposal involves the creation of a single storey basement under the full footprint of an existing detached multi occupancy residential property.
- 1.6. A Screening Assessment has been undertaken, informed by a Desk Study. An outline construction programme and utilities information has been provided in the updated submissions.
- 1.7. A ground investigation confirms that the basement will be founded within the London Clay, and that groundwater is not expected to be encountered. It is accepted that the development will not impact on the wider hydrogeological environment.
- 1.8. The basement will be formed by underpinning and sheet piling techniques. In order to support the internal walls, plunge columns will be installed.
- 1.9. The impermeable site area will not significantly increase as a result of the proposed basement. It is accepted that the development will not impact on the wider hydrological environment and the site is not subject to flooding.
- 1.10. A ground movement assessment (GMA) has been undertaken and a damage assessment is provided indicating damage to be within Category 1, supported by additional analysis / evidence in the updated submissions.
- 1.11. Proposals are provided for a movement monitoring strategy.
- 1.12. Considering the updated submissions, the BIA complies with the requirements of CPG: Basements.

2.0 INTRODUCTION

- 2.1. CampbellReith was instructed by the London Borough of Camden (LBC) on 21st January 2022 to carry out a Category B audit on the Basement Impact Assessment (BIA) submitted as part of the Planning Submission documentation for 1 Wadham Gardens, London, NW3 3DN and Planning Reference 2021/6174/P.
- 2.2. The audit was carried out in accordance with the Terms of Reference set by LBC. It reviewed the Basement Impact Assessment for potential impact on land stability and local ground and surface water conditions arising from basement development.
- 2.3. A BIA is required for all planning applications with basements in Camden in general accordance with policies and technical procedures contained within
- Camden Local Plan 2017 - Policy A5 Basements.
 - Camden Planning Guidance (CPG): Basements. January 2021.
 - Guidance for Subterranean Development (GSD). Issue 01. November 2010. Ove Arup & Partners.
- 2.4. The BIA should demonstrate that schemes:
- maintain the structural stability of the building and neighbouring properties;
 - avoid adversely affecting drainage and run off or causing other damage to the water environment;
 - avoid cumulative impacts upon structural stability or the water environment in the local area;
 - and evaluate the impacts of the proposed basement considering the issues of hydrology, hydrogeology and land stability via the process described by the GSD and to make recommendations for the detailed design.
- 2.5. LBC's Audit Instruction described the planning proposal as *"Excavation of single-storey basement level under footprint of existing building, sunken terrace to north-west of site, 4x front and side light-wells with grilles, internal alterations to flats on ground, first and second floors, new and altered window openings to rear ground floor and first floor level, demolition and rebuild of the north-west end of the building, new boundary treatment and landscaping works, in association with 6 existing dwellings"*.
- 2.6. The Audit Instruction confirmed 1 Wadham Gardens did not involve, or was a neighbour to, listed buildings.
- 2.7. CampbellReith accessed LBC's Planning Portal on 2 February 2022 and gained access to the following relevant documents for audit purposes:
- Ground Appraisal Report. Geo-Environmental Services Ltd, Version 3.0 – December 2018.
 - Structural Calculations and Basement Impact Assessment (BIA) by Quadrant Harmon Consulting Ltd, Ref No. – SOH/1550/23, Rev 5, dated 15 December 2021.
 - Construction Management Plan. HUB Architects, Issue 1, Ref No. – 1179-App-02, Dated 24th November 2021.

- Arboricultural Impact Assessment Report by Landmark Trees dated 30th November 2021.
- HUB Architects and Designers Ltd and Quadrant Harmon Consulting Ltd Planning Application drawings:
 - Proposed Block Plan (1179-00)
 - Existing Plans (1179-01)
 - Proposed Plans (1179-01)
 - Existing Elevations (1179-02)
 - Proposed Elevations (1179-02)
 - Existing Sections (1179-03)
 - Proposed Sections (1179-03)
 - Proposed Plans Soft and Hard Landscaping (1179-10-B)
 - Proposed Site Plan Diagram (1179-PL-01)
 - Underpinning, Temporary Works & Sequence (1550-01-2)
 - Basement Plan (1550-02-3)
 - Temporary propping (1550-04-1)

2.8. CampbellReith were provided with the following relevant documents for audit purposes between February and May 2022:

- Ground Appraisal Report. Geo-Environmental Services Ltd, Version 4.0 – May 2022.
- Outline Construction programme by HUB Architects
- Utilities Report by Envirocheck

3.0 BASEMENT IMPACT ASSESSMENT AUDIT CHECK LIST

Item	Yes/No/NA	Comment
Are BIA Author(s) credentials satisfactory?	Yes	
Is data required by Cl.233 of the GSD presented?	Yes	
Does the description of the proposed development include all aspects of temporary and permanent works which might impact upon geology, hydrogeology and hydrology?	Yes	
Are suitable plan/maps included?	Yes	
Do the plans/maps show the whole of the relevant area of study and do they show it in sufficient detail?	Yes	
Land Stability Screening: Have appropriate data sources been consulted? Is justification provided for 'No' answers?	Yes	
Hydrogeology Screening: Have appropriate data sources been consulted? Is justification provided for 'No' answers?	Yes	
Hydrology Screening: Have appropriate data sources been consulted? Is justification provided for 'No' answers?	Yes	

Is a conceptual model presented?	Yes	Described within Sections 7 and 8
Land Stability Scoping Provided? Is scoping consistent with screening outcome?	Yes	Section 5.1 of the BIA listing potential impacts.
Hydrogeology Scoping Provided? Is scoping consistent with screening outcome?	NA	No potential impacts carried over from screening.
Hydrology Scoping Provided? Is scoping consistent with screening outcome?	NA	No potential impacts carried over from screening.
Is factual ground investigation data provided?	Yes	Section 6.0 and Appendix B of the BIA.
Is monitoring data presented?	Yes	Section 7.3 of the BIA.
Is the ground investigation informed by a desk study?	Yes	Section 2.0 of the BIA along with supporting information in Appendix A.
Has a site walkover been undertaken?	Yes	
Is the presence/absence of adjacent or nearby basements confirmed?	No	However, no neighbouring basements assumed in damage assessment (conservative).
Is a geotechnical interpretation presented?	Yes	Section 7.0 and 8.0 of the BIA.
Does the geotechnical interpretation include information on retaining wall design?	Yes	Section 8.4 of the BIA.
Are reports on other investigations required by screening and scoping presented?	NA	

Are the baseline conditions described, based on the GSD?	Yes	
Do the base line conditions consider adjacent or nearby basements?	No	However, no neighbouring basements assumed in damage assessment (conservative). No groundwater flow impacts assessed.
Is an Impact Assessment provided?	Yes	
Are estimates of ground movement and structural impact presented?	Yes	Section 9.0 of the BIA.
Is the Impact Assessment appropriate to the matters identified by screening and scoping?	Yes	
Has the need for mitigation been considered and are appropriate mitigation methods incorporated in the scheme?	Yes	
Has the need for monitoring during construction been considered?	Yes	Section 9.5 of the BIA.
Have the residual (after mitigation) impacts been clearly identified?	Yes	Updated submission.
Has the scheme demonstrated that the structural stability of the building and neighbouring properties and infrastructure will be maintained?	Yes	GMA updated to consider ground movements due to underpin and sheet pile installations.
Has the scheme avoided adversely affecting drainage and run-off or causing other damage to the water environment?	Yes	
Has the scheme avoided cumulative impacts upon structural stability or the water environment in the local area?	Yes	Updated submission.

Does report state that damage to surrounding buildings will be no worse than Burland Category 1?	Yes	GMA updated to limit damage to surrounding buildings within Category 1 of the Burland Scale.
Are non-technical summaries provided?	Yes	Quadrant Harmon Consulting Ltd BIA Report

4.0 DISCUSSION

- 4.1. The Basement Impact Assessment (BIA) was undertaken by Geo-Environmental Services Limited and Quadrant Harmon Consulting Ltd. In the revised submission, it has been demonstrated that the authors hold qualification in accordance with CPG Basements.
- 4.2. The site is located on the south-west side of Wadham Gardens within the Elsworthy Conservation area in the London Borough of Camden. The audit instruction identified that the basement proposal neither involved, nor was neighbouring to, a listed building.
- 4.3. The site comprises an approximately rectangular shaped parcel of land occupied by a one to two storey detached property, with a multi occupancy residential use. The building is of traditional load bearing masonry construction and some alterations and extensions have been carried out historically, noticeably a single storey extension with roof terrace to the north.
- 4.4. The proposal is to demolish the northern extension and to reconstruct it in a different configuration, to create a single storey basement under the full plan of the property, along with a basement level terrace to the north-west, two lightwells to the south and two lightwells to the east. The majority of the basement perimeter walls will be positioned directly beneath the existing masonry walls and the walls will be formed by reinforced concrete in an underpinning sequence. The maximum excavation depth is approximately 3.50m below ground level (bgl).
- 4.5. A Screening Assessment has been undertaken, informed by a Desk Study, broadly in accordance with LBC guidance. An outline construction programme and utilities information has been provided in the updated submission.
- 4.6. A ground investigation undertaken by Geo-Environmental Services Ltd in September 2015 identified Made Ground to a maximum depth of 0.60m bgl underlain by the London Clay Formation which was proven to 4.60m bgl. Although groundwater was not encountered during the ground investigation, two standpipes were installed and groundwater was monitored during four visits, between 2.12m and 3.16m bgl, above the proposed basement level. The BIA concluded those levels represent an accumulation of perched water in the standpipes rather than a continuous groundwater body. However, the BIA considers the potential for groundwater ingress during construction and indicates mitigation measures to be implemented as part of the temporary works. The London Clay is designated unproductive strata. There will be no impact to the wider hydrogeological environment.
- 4.7. The structural drawings indicate four lightwells are to be built utilising sheet piling that will be hydraulically driven in a vibrationless manner. The remaining retaining walls are to be formed by underpinning techniques, with structural drawings indicating construction in 2-stages. The basement slab is to be a ground bearing reinforced concrete slab tied into the toes of the L shaped stem bases and will provide a permanent base prop to the retaining walls.
- 4.8. The ground floor construction is to be replaced with a suspended reinforced concrete slab that will span between the underpinned walls and internal reinforced concrete columns. In order to support the internal walls, temporary plunge piles will be installed and post construction these will be used as tension piles beneath the basement to reduce heave. Preliminary calculations have been produced in order to estimate heave forces per pile and pile capacity.

- 4.9. The impermeable site area will not significantly increase as a result of the proposed basement. It is accepted that the development will not impact on the wider hydrological environment and the site is not subject to flooding.
- 4.10. A Ground Movement Assessment (GMA) is provided in Section 9.0 of the Ground Appraisal Report. Maximum vertical movements due to excavation in the short and long term have been calculated using a Pdisp model and are 12mm and 18mm respectively.
- 4.11. An updated Xdisp model has been produced to estimate ground movements due to basement construction by underpinning in accordance with CIRIA C580 (now replaced by CIRIA C760), with the underpinned sections being treated as bored piles. Whilst the CIRIA approach is intended for embedded retaining walls, it is accepted that the predicted ground movements are within the range typically anticipated for underpinning techniques carried out with good control of workmanship.
- 4.12. Monitoring data from a similar project constructed with 2 stages of underpinning has been provided to demonstrate that, with the temporary works proposed and close control of construction, movements can be maintained within the limits predicted.
- 4.13. Section 9.4 of the report includes a damage assessment in accordance with the Burland scale, with damage to neighbouring structures indicated to be Category 0 to Category 1 (Negligible to Very Slight). Correspondence with the author confirms that other apartments within the building are owned by the Applicant and will be vacant during the proposed construction works, with any additional remediation works required to internal finishes being carried out during the basement construction works.
- 4.14. Although movements generated by sheet piling are stated to be negligible in the BIA, published guidance indicates that movements can occur. It is noted, however, that sheet piling is to be undertaken in short, localised runs away from neighbouring properties and therefore this assessment is accepted.
- 4.15. A movement monitoring strategy is provided in Section 9.5 and trigger levels are presented in the structural drawing (GN02).

5.0 CONCLUSIONS

- 5.1. In the updated submissions, the authors of the BIA have been demonstrated to hold qualifications in accordance with CPG Basements 2021.
- 5.2. A Screening Assessment has been undertaken, informed by a Desk Study.
- 5.3. In the updated submissions, an outline construction programme and utilities information is provided.
- 5.4. A ground investigation confirms that the basement will be founded within the London Clay. It is accepted that the development will not impact on the wider hydrogeological environment.
- 5.5. The basement will be formed by 2-stage underpinning and sheet piling techniques.
- 5.6. It is accepted that the development will not impact on the wider hydrological environment and the site is not subject to flooding.
- 5.7. A ground movement assessment has been undertaken and subsequent damage assessment indicate damage to be within Category 1 (Very Slight). In the updated submissions, supporting evidence has been provided to justify movement predictions.
- 5.8. Proposals are provided for a movement monitoring strategy.
- 5.9. Considering the updated submissions, it can be confirmed that the BIA complies with the requirements of CPG: Basements.

Appendix 1: Consultation Responses

None

Appendix 2: Audit Query Tracker

Audit Query Tracker

Query No	Subject	Query	Status	Date closed out
1	BIA Format	It should be demonstrated that the authors of the BIA possess qualifications in accordance with CPG Basements 2021.	Closed	May 2022
2	BIA Format	An outline construction programme and utilities information should be provided.	Closed	April 2022
3	Land Stability	GMA to be reviewed, as comments in Section 4.	Closed	April 2022
4	Land Stability	Trigger levels for movement monitoring to be reviewed following any revisions to the GMA.	Closed	April 2022

Appendix 3: Supplementary Supporting Documents

Correspondence from BIA Authors

To ""ansaffashraff@campbellreith.com"" <ansaffashraff@campbellreith.com>,
Cc "Stuart Harmon (stuart.harmon@quadrantharmon.co.uk)"
 <stuart.harmon@quadrantharmon.co.uk>, "Katie Brayne" <katie.brayne@gesl.net>,
Bcc
Subject 1 Wadham Gardens
From "Jonathan Tingley" <Jonathan.Tingley@gesl.net> - Wednesday 06/04/2022 17:31

Dear Ansaff,

Further to our discussion last week please find below a link to additional supporting information.

We prepared a BIA for a project in Fairholt Street, Westminster in 2015. The project involved a double basement and was carried out in two stages using traditional underpinning. Below is a link to the tilt monitoring and survey data. In the folder, there are two sub folders, the first has monitoring data covering the demolition of internal walls etc. and the second is for the readings taken during the underpinning. Also in the folder is the structural method statement for the works.

[\[Suspicious URL detected\]](#)

Within the comprehensive dataset the surveying records minimal movements during the works with all readings remaining within the 'green' zone indicating less than 5mm of total movement.

Please can you confirm that you're happy with this additional information and that Query No. 3 relating to the comments in Section 4 of your audit report can be closed out? I'm on annual leave next week, so please copy in Stuart Harmon to any responses.

Jonathan Tingley

CEnv, BEng (Hons), MSc, FGS, MIEEnvSc
Technical Director

T: +44 (0) 1273
832972

M: +44 (0) 7866
434182

W: www.gesl.net

Head office: Unit 7, Danworth Farm, Cuckfield Rd, Hurstpierpoint, West Sussex, BN6 9GL, UK
Bristol Office: Bristol Broad Quay, Broad Quay House, Prince Street, Bristol, BS1 4DJ
Birmingham Office: Birmingham Fort Dunlop, Fort Dunlop, Fort Parkway, Birmingham, B24 9FEL



Geo-Environmental

Geo-Environmental Services Limited has ISO9001, ISO14001 and OHSAS18001 accreditation.
The Company Registration No. is 3214980 and the VAT Registration No. is 679544479.

TALK Listen change lives

time to talk day 03/02/22

However you do it, start a conversation about mental health

In partnership with

Click [here](#) to report this email as spam.

London

15 Bermondsey Square
London
SE1 3UN

T: +44 (0)20 7340 1700
E: london@campbellreith.com

Birmingham

Chantry House
High Street, Coleshill
Birmingham B46 3BP

T: +44 (0)1675 467 484
E: birmingham@campbellreith.com

Surrey

Raven House
29 Linkfield Lane, Redhill
Surrey RH1 1SS

T: +44 (0)1737 784 500
E: surrey@campbellreith.com

Manchester

No. 1 Marsden Street
Manchester
M2 1HW

T: +44 (0)161 819 3060
E: manchester@campbellreith.com

Bristol

Unit 5.03,
HERE,
470 Bath Road,
Bristol BS4 3AP

T: +44 (0)117 916 1066
E: bristol@campbellreith.com

Campbell Reith Hill LLP. Registered in England & Wales. Limited Liability Partnership No OC300082
A list of Members is available at our Registered Office at: 15 Bermondsey Square, London, SE1 3UN
VAT No 974 8892 43