




**LEVEL MONITORING - RELATIVE SURVEY READINGS**

<b>Provider Details</b>		<b>Client Details</b>		<b>Risk Address</b>	
Name:	MHN Ltd	Insurance Co.:		Occupier:	19 College Crescent Ltd
Date of Issue:	10/3/22	Client Name:	Davies Group Limited	Address:	19 College Crescent
		Technical Mgr:	Jessica Moran	Address:	London
		Email:	[REDACTED]	Town:	
		Client Ref:		County:	
		Address:	Davies Group Limited	Post Code:	NW3 5LL
<b>Monitoring Details</b>		Address:	Subsidence and Surveying Services	Tel Home:	
Instruction Date:	19/11/20	Address:	PO Box 2598	Tel Work:	
First Reading Date:	25/11/2020	Town:	Stoke on Trent	Mobile:	[REDACTED]
Maximum No Visits:	UFN	Post Code:	ST4 9EY	Other:	
Anticipated Expiry Date:	TBC	Other Email:			
Monitoring Int:	2 Monthly				

		Target Date:													
		Reading Date:													
		Issue Date:													
Row No.	Point Name	X Co-ordinate	Y Co-ordinate	1	2	3	4	5	6	7	8	9	10	11	12
1	1	0.00	0.00	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000		
2	2	-4.90	0.00	10.0248	10.0249	10.0253	10.0247	10.0246	10.0250	10.0248	10.0249				
3		-5.00	0.00												
4	3	-5.00	-1.40	9.9502	9.9507	9.9509	9.9506	9.9503	9.9497	9.9509	9.9501				
5		-5.00	-1.50												
6	4	-7.50	-1.50	12.5940	12.5946	12.5952	12.5945	12.5936	12.5954	12.5948	12.5963				
7	5	-7.50	10.00	10.2638	10.2644	10.2644		10.2642	10.2644	10.2643	10.2642				
8	6	-3.50	10.00	9.9538	9.9549	9.9559		9.9562	9.9557	9.9561	9.9553				
9	7	0.00	10.00	10.0000	10.0000	10.0000		10.0000	10.0000	10.0000	10.0000				
10															
11															
12															
13															
14															
15															
16															
17															
18															
19															
20															
21															
22															
23															
24															
25															
26															
27															
28															
29															
30															
31															
32															



- 10/03/2022
- No new concerns raised at time of visit.
- It was not possible to install all stations within the same brick course. Therefore initial readings cannot be interpreted as Distortion Data.
- Front readings have been made relative to level station 1 & rear readings have been made relative to level station 7. They have assumed value of 10.0000m. If this is not appropriate, please advise if a deep datum is required?
- Further readings to be taken May 22