



No. 56

No. 58

No. 60



Location of Existing Garden Door

1

Argyle Walk

- NOTES:
1. Existing door
  2. Matching new timber door painted black to replace the existing door.
  3. Existing boundary wall render make good.
- Site Boundary



Photograph of Existing Garden Door



client:  
**Mike Thomas + Hugh Webb**

project:  
**58 Argyle Street  
Kitchen and Pantry Refurbishment**

drawing status: <b>Planning</b>	job no: <b>893</b>	size: <b>A3</b>	drawn by: <b>AG</b>	<table><tr><td>-</td><td>14/06/22</td><td>Issued for Planning</td><td>AG</td></tr><tr><td>rev</td><td>date</td><td>description</td><td>by</td></tr><tr><td colspan="4">drawing amendments</td></tr></table>	-	14/06/22	Issued for Planning	AG	rev	date	description	by	drawing amendments			
-	14/06/22	Issued for Planning	AG													
rev	date	description	by													
drawing amendments																
drawing: <b>Existing and Proposed Garden Door</b>	drawing no: <b>057</b>	scale: <b>1:50</b>	revision no: <b>-</b>													