

original dividing (party) wall to adjoining house - existing Roman cement in-situ run cornice over terracotta creasing tiles evidence original coping provision to wall

portland cement moulding to match original re-run with swept detail to connect original coping level to reduced wall height. Roman cement band on adjoining property side aligns with saltaire detailed wall on opposite corner of Inverness Street/Gloucester Crescent junction

Portland cement moulding and swept curve removed

decayed soldier course coping removed

