

Rotten window removed/replaced

uPVC rainwater pipe to be removed/replaced

Partially collapsed chimneybreast to be rebuilt

Below pavement vault

CONTRACTORS TO VERIFY ALL DIMENSIONS ON SITE BEFORE COMMENCING ANY WORKS OR PREPARING SHOP DRAWINGS. ALL WORK MUST COMPLY WITH RELEVANT AUTHORITIES REQUIREMENTS. DIMENSIONS MUST NOT BE SCALED FROM THIS PRINT

Landers & Associates

Chartered Surveyors

67 Riefeld Road, London SE9 2RA
Tel: 020 7831 6311 Web: www.landars-associates.co.uk

Client - The Governing Body Rugby School

Job - 59 Lambs Conduit Street, London WC1

Drawing - Basement Demolition Plan

Scale	Date	Drawn	Checked
1:50@A3	Jun 22	MR	RS

Drawing No. - 21016-104