

PROJECT TITLE: GLOUCESTER LODGE

PROJECT NUMBER: 2104287 FILE: Site Visit Report 20220429 (R1)

SITE VISIT BY: CC DATE: 29 April 2022

REPORT BY: CC DATE: 03 May 2022

ADDRESS OF SITE: MEWS HOUSE, PART OF 12 GLOUCESTER GATE. LONDON NW1 4HG

Introduction & Progress

A site visit was made by Techniker Consulting Engineers to carry out a photographic survey of Gloucester Lodge Mews looking specifically at the East façade that is to be retained. The purpose of the survey was to record the condition of the wall prior to the works. Conditions were clear and calm.

A follow-up survey will be carried out on completion of the works.

Photographs

The following pages contain photographs with location references. The plan at the end of the report (drawing 2104287-1008) shows the locations and directions in which the photographs were taken.

Where defects were observed they have been indicated on the photographs and are noted below.

Observations

Photos 9, 10 & 11 show a horizontal crack in each side of a section of wall supporting a beam.

External Façade Photos

Location 1



Location 2



Location 3



Location 4



Location 5



Internal Photos

Location 6



Location 7



Location 8



Location 8.1



Location 9



Enlargement of Location 9



Location 10 – visible crack circled




Location 11 – visible crack circled



Location 11.1



Location 12



Location 13



Location 14



Location 15



Location 16



