



PHD ASSOCIATES LLP

Consultants in Architecture, Planning, Property Development & Construction

Braemar House, Water Lane, Stansted, Essex, CM24 8BJ - website : www.PHDAssociates.co.uk - Tel. 01279-817342 x100 - EMail: info@phdassociates.co.uk



Project Ref. No:

2105- WINDOW and EXTERNAL DOOR SCHEDULE - Oxford House Hostel, Tavistock Place, London, WC1H 9RE

Rev (-)

18/08/2022

General notes:

Refer to general arrangement plan drawings 2105-BC-(A)-401/402/403 and Elevations drawings 2105-BC-E-501/502/503 and Window report document for location and photograph of existing state.

*Glass to match the existing in weight and thickness

WINDOWS

Floor No.	Name	Location		Description	Type	Glass	Drawing Ref
BF- Basement Floor	W-1-01	Room 1	Front elevation	Existing - To be restored	Sash	Single Glazing *	2105-BC-J-001/101
	W-1-02	Room 15	Front elevation	Existing - To be restored	Sash	Single Glazing *	2105-BC-J-001/101
	W-1-03	Room 2	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W-1-04	Room 14	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W-1-05	Bathroom BC (Room 2)	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W-1-06	Technical room	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W-1-07	Room 17	Front elevation Annexe	New sash window	Sash	Single Glazing *	2105-BC-J-002/102
	W-1-08	Room 16	Front elevation Annexe	New sash window	Sash	Single Glazing *	2105-BC-J-002/102
	W-1-09	Bathroom BD (Room 17)	Front elevation Annexe	New Window.	Fixed window	Single Glazing *	2105-BC-J-003/103
	W-1-10	Bathroom BD (Room 16)	Front elevation Annexe	New Window.	Fixed window	Single Glazing *	2105-BC-J-003/103
	W-1-11	Bathroom BD (Room 18)	Front elevation	Existing - To be restored	Fixed window	Single Glazing *	2105-BC-J-005/105
	W-1-12	Bathroom BC (Room 2)	Front elevation	New Window.	Fixed window	Single Glazing *	2105-BC-J-005/105
	W-1-13	Bathroom BB (Room 15)	Front elevation	Removed	Casement	Single Glazing *	>
GF-Ground floor	W0-01	Room 3	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W0-02	Room 3	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W0-03	Room 19	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W0-04	Room 19	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W0-05	Room 4	Rear elevation	Existing - To be restored	Sash	Single Glazing *	>
	W0-06	Store room 1	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W0-07	Store room 1	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W0-08	Store room 2	Rear elevation	New Window.	Casement	Single Glazing *	2105-BC-J-004/104
	W0-09	Store room 2	Rear elevation	Existing - To be restored	Casement	Single Glazing *	2105-BC-J-004/104
	W0-10	Room 18	Rear elevation	Existing - To be restored	Sash	Single Glazing *	>
oor	W1-01	Room 6	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W1-02	Room 7	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W1-03	Room 21	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W1-04	Room 22	Front elevation	Existing - To be restored	Sash	Single Glazing *	>

1F First fl	W1-05	Room 5	Rear elevation	Existing - To be restored	Sash	Single Glazing *	>
	W1-06	Room 20	Rear elevation	Existing - To be restored	Sash	Single Glazing *	>
	W1-07	Bathroom BG(Shared)	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W1-08	Bathroom BG(Shared)	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W1-09	Laudry room	Rear elevation	New Window.	Casement	Single Glazing *	2105-BC-J-004/104
	W1-10	Laudry room	Rear elevation	Existing Window.	Casement	Single Glazing *	2105-BC-J-004/104
2F Second floor	W2-01	Room 9	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W2-02	Room 10	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W2-03	Room 24	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W2-04	Room 25	Front elevation	Existing Window.	Sash	Single Glazing *	>
	W2-05	Room 8	Rear elevation	Existing - To be restored	Sash	Single Glazing *	>
	W2-06	Room 23	Rear elevation	Existing - To be restored	Sash	Single Glazing *	>
	W2-07	Store room 4	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W2-08	Store room 4	Rear elevation	Existing - To be restored	Casement	Single Glazing *	>
	W2-09	Common stair No.30	Rear elevation	Existing - To be restored	Sash	Single Glazing *	>
3F Third floor	W3-01	Room 12	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W3-02	Room 13	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W3-03	Room 27	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W3-04	Room 28	Front elevation	Existing - To be restored	Sash	Single Glazing *	>
	W3-05	Room 11	Rear elevation	Existing - To be restored	Casement	Single Glazing *	2105-BC-J-006/106
	W3-06	Common stair No.32	Rear elevation	New Window.	Casement	Single Glazing *	2105-BC-J-006/106
	W3-07	Room 26	Rear elevation	Existing - To be restored	Casement	Single Glazing *	2105-BC-J-007/107
	W3-08	Common stair No.30	Rear elevation	New Window.	Casement	Single Glazing *	2105-BC-J-007/107
EXTERNAL DOOR							
	ED-1-1	Front door No.32	Front elevation	Existing - To be restored			>
	ED-1-2	Front door No.30	Rear elevation	Existing - To be restored			>
	ED-1-3	Front door Room 17	Rear elevation	Existing - To be restored			>
	ED-1-4	Front door Room 16	Front elevation	Existing - To be restored			>
	ED-1-5	Corridor External door	Rear elevation	Existing - To be restored			2105-BC-J-008/108
	ED-1-6	Access to little patio	Rear elevation	New Door			2105-BC-J-008/108