



Appendix 3 Desk Study References

Figure 3 Site Location Plan



The site comprises a three-storey end of terrace residential property.

Figure 4 Historical Map Extract, OS 1:2,500 1870-1871




Figure 5 Historical Map Extract, OS 1:10,560 1894




Figure 6 Historical Map Extract, OS 1:2,500 1915




Figure 7 Historical Map Extract, OS 1:2,500 1953-55




Figure 8 Historical Map Extract, OS 1:1, 250 1991





Figure 9 WW2 Bomb Damage Map Extract



Figure 10 Slope Angle and Worked Ground Map, LB Camden (GHHS figure 16)



Slopes in green, 7 – 10 degrees; Slopes in purple, >10 degrees.

Figure 11 Geological Map Extract, BGS (Geology of Britain Viewer)





Figure 12 Flooded Streets Map, LB Camden (GHHS Figure 15)



The highlighted streets are known to have flooded in 1975 (light blue) and 2002 (dark blue).

Figure 13 Flood Risk Map, Environment Agency (Surface Water Flood Risk)



Extent of flooding from surface water

● High
 ● Medium
 ● Low
 ● Very low
 ⊕ Location you selected

Figure 14 Groundwater Source Protection Zone, LB Camden (GHHS Figure 8)




Figure 15 Lost Rivers of London, Barton (LB Camden GHHS Figure 11)



Figure 16 Transport for London Property Asset Register

