

Haverstock Hill Laurel Tree

Laurel tree causing structural damage to party wall

14 Sep 2022

Project Details

Name: Haverstock Hill Laurel Tree

Summary: Laurel tree causing structural damage to party wall


Client Company: Origin Housing



Total Issues: 2




Item 1



Description

Bay Laurel tree roots spreading

Item 2



Description

Visible structural damage to party wall