Quinn Architects

Project 29 Great James Street

Code QA202

Date 23rd June 2022

Change since last revision

Revision	Issue Date	Issued for	
Α	26/10/21	Design team review	
В	03/11/21	Planning	
С	23/06/22	Planning	

Code	Location	Existing Condition	Photo	Proposed Condition			
Basement							
FB.01	Bed (B04)	No fireplace. Interior used as cupboard to house boiler.		No fireplace. Opening to be closed up and vent installed.			
FG.01	Dining (G01)	 Non-original stone surround and interior Hearth concealed, condition unknown 		 New stone surround, early Georgian style Cast iron slips Exposed brick fireback Hearth to be assessed. If not salvageable, install new stone hearth. 			
FG.02	Reception (G12)	 Simple moulded mantlepiece Cast iron firebox Marble hearth 		 Surround appears correct period and style. To be retained and refurbished. Basket removed. New cast iron slips Exposed brick fireback Functioning open fire in cast iron basket 			
F1.01	Living (101)	Stone regency style surround (too late for period of house) Metal slips Cast iron firebox and integrated basket Stone hearth		 New stone surround, early Georgian style Cast iron slips Exposed brick fireback New wood burning insert Hearth to be assessed. If not salvageable, install new stone hearth. Functioning open fire in cast iron basket 			
F1.02	Office (103)	Stone regency style surround (too late for period of house) Metal slips Cast iron firebox and integrated basket Hearth obscured by finishes - condition unknown		 New stone surround, early Georgian style Cast iron slips Exposed brick fireback New basket with biofuel burner Hearth to be assessed. If missing, install new stone hearth. 			

A904 Fireplace Schedule Revision C Page 1

A904 Fireplace Schedule

Project 29 Great James Street

Code QA202

Date 23rd June 2022

Code	Location	Existing Condition	Photo	Proposed Condition
F2.01	Bedroom (201)	Simple moulded mantlepiece Metal slips Cast iron firebox with tiled sides and integrated basket Hearth obscured by finishes - condition unknown		 Surround appears of the correct period and style. To be retained and refurbished. New cast iron slips. Exposed brick fireback New basket with biofuel burner
F2.02	Bathroom (205)	Simple moulded mantlepiece Metal slips Cast iron firebox Hearth obscured by finishes - condition unknown		 Surround and interior appear of the correct period and style. All to be retained and refurbished. Hearth to be assessed. If missing, install new slate hearth. New basket with biofuel burner
F3.01	Ensuite (309)	 Plain faced surround, painted - potentially stone. Appears correct for the period. Interior blocked 		 Surround appears of the correct period and style. To be retained and refurbished. New cast iron slips. Hearth to be assessed. If missing, install new stone hearth. Exposed brick fireback New basket with biofuel burner

A904 Fireplace Schedule Revision C Page 2