

The attached Figure below substitutes Fig 13.5 to address higher resolution issues and the lack of the red line of the site boundary.





The attached Figure below substitutes Fig 13.6 to address higher resolution issues and the lack of the red line of the site boundary.





The attached Figure below substitutes Fig 13.7 to address higher resolution issues and the lack of the red line of the site boundary.



Proposed: Winter Safety Map

LEGEND: Safe Unsafe




The attached Figure below substitutes Fig 13.8 to address higher resolution issues and the lack of the red line of the site boundary.






The attached Figure below substitutes Fig 13.9 to address higher resolution issues.






The attached Figure below substitutes Fig 13.10 to address higher resolution issues.






The attached Figure below substitutes Fig 13.11 to address higher resolution issues and the lack of the red line of the site boundary.






The attached Figure below substitutes Fig 13.12 to address higher resolution issues.



The attached Figure below substitutes Fig 13.13 to address higher resolution issues.



The attached Figure below substitutes Fig 13.14 to address higher resolution issues and the lack of the red line of the site boundary.

