

Appendix A

Photographic Schedule

Supporting document for: Listed Building Consent application.

Project: Replacement of flat entrance door sets.

Location: Bourne Estate, Portpool Lane, London, EC1N.

Client: London Borough of Camden

CONTACTS



LAURA REYNOLDS
Consultant

m ++44 (0)7899310878

e laura.reynolds@arcadis.com

Arcadis Consulting (UK) Ltd

16th Floor,

103 Colmore Row,
Birmingham

B3 3AG | United Kingdom

Version Control (optional)

Version	Date	Author	Checker	Approver	Changes
Draft	08/09/2022	LR			
QA	20/09/2022	LR	NG		
Final	21/12/2022	LR		Client	

This report dated 21 December 2022 has been prepared for London Borough of Camden (the “Client”) in accordance with the terms and conditions of appointment between the Client and **Arcadis Consulting (UK) Limited** (“Arcadis”) for the purposes specified in the Appointment. For avoidance of doubt, no other person(s) may use or rely upon this report or its contents, and Arcadis accepts no responsibility for any such use or reliance thereon by any other third party.

Contents

1 Introduction	5
1.1 Location Plan	6
2 Schedule of Existing flat entrance doors.....	7


1 Introduction

This document is intended to provide an illustrative overview of existing flat entrance door sets in each housing block of the Bourne Estate, London EC1N. It is intended to demonstrate the proportion of historic fabric against modern replacements, and thus assist those in assessing an application for Listed Building Consent to replace these doors.



This document should be read in conjunction with the Design and Access statement incorporating Heritage Statement submitted as part of the proposal.

This report has been prepared by Laura Reynolds BSc(Hons) MSc MRICS, Building Surveyor at Arcadis.

This report has been prepared with the sole purpose being to support an application for Listed Building Consent on behalf of the London Borough of Camden and should not be used for any other purpose





2 Schedule of Existing flat entrance doors

Location	Description	Photographic examples			
Nigel House.	<p>Flat entrance doors are set out across the ground floor and upper concrete walkways.</p> <p>Of 48 doors, none appear to be original.</p>				
Buckbridge House.	<p>Flat entrance doors are set out across the ground floor and internal access corridors.</p> <p>Of 30 doors, 5 appear to be original. These are represented by the first and second image.</p>				

Appendix A

Location	Description	Photographic examples			
Kirkeby House.	<p>Flat entrance doors are set out across the ground floor, external concrete walkways and internal access corridors.</p> <p>Based upon the available 1909 image contained within the main report, none of the doors within this block appear to be original.</p>				
Redman House.	<p>Flat entrance doors are set out across the ground floor, external concrete walkways and internal access corridors.</p> <p>Of 82 doors, approximately 13 appear to be original or altered originals. These are represented by the first and second photos.</p>				



Appendix A

Location	Description	Photographic examples	
<p>Laney House</p>	<p>Flat entrance doors are set out across the ground floor, external concrete walkways and internal access corridors.</p> <p>Of 41 doors, none appear to be original.</p>		
<p>Shene House</p>	<p>Flat entrance doors are set out across the ground floor and external concrete walkways.</p> <p>Of 17 doors, 5 appear to be original or altered originals. These are represented by the second and third photographs.</p>		






Appendix A

Location	Description	Photographic examples
Radcliffe House	<p>Flat entrance doors are set out across the ground floor, external concrete walkways and internal access corridors.</p> <p>Of 61 doors, none appeared to be original.</p>	
Skipwith House	<p>Flat entrance doors are set out across the ground floor and external concrete walkways.</p> <p>Of 30 doors, none appeared to be original.</p>	

Appendix A

Location	Description	Photographic examples
<p>Denys House.</p>	<p>Flat entrance doors are set out across the ground floor and external concrete walkways.</p> <p>Of 30 doors, 5 appear to be original or altered originals. These are represented by the first and second images.</p>	
<p>Ledam House</p>	<p>Flat entrance doors are set out across the ground floor and external concrete walkways.</p> <p>Of 34 doors, 5 appear to be original or altered originals. These are represented by the first image.</p>	

Appendix A

Location	Description	Photographic examples
Scrope House	<p>Flat entrance doors are set out across the ground floor and external concrete walkways.</p> <p>Of 34 doors, 6 appear to be original or altered originals. These are represented by the first image.</p>	 
Frewell House	<p>Flat entrance doors are set out across the ground floor and external concrete walkways.</p> <p>Of 30 doors, none appear to be original.</p>	  

Arcadis Consulting (UK) Limited

80 Fenchurch Street
London EC3M 4BY
United Kingdom

T: +44 (0)20 7812 2000

[arcadis.com](https://www.arcadis.com)