

Ref _____

Insured _____

Date _____

Time _____


Meeting with _____



Front elevation




Hairline left of bay




Crack in hall ceiling



Crack in kitchen ceiling



Crack in kitchen ceiling



Crack in coving in rear of kitchen

Ref _____

Insured _____


Date _____

Time _____

Meeting with _____




Crack in ceiling in dining room 3mm



Crack down wall in living room



Crack below bay in living room



Crack along ceiling in first floor hallway



Crack on left wall of first floor hallway 10mm



Bed 3-2mm Crack along ceiling

Ref _____

Insured _____

Date _____

Time _____


Meeting with _____




Separation crack between window and wall bed 3



Hairline cracks on right of window in bathroom



Crack along ceiling in bedroom 2



Separation crack down wall in bed 2



Crack on ceiling in master bedroom



2nd floor hallway crack on ceiling


Ref _____

Insured _____

Date _____

Time _____

Meeting with _____



2nd floor hallway crack on
ceiling