

W.03.07

NOTES :

Modern casement
 Post condition
 Frosted glass

1920s sash window with
 obscured glazing. No panelling
 or
 other detail beyond modest
 architrave.



W.02.10

NOTES :

Weighted sash
 6 panel sashes
 OK condition

1920s window with horns in new
 opening. The stair windows to
 no. 34 appear to have been
 reconfigured. No panelling or
 other detail of interest.



W.01.10

NOTES :

Weighted sash
 6 panel sashes
 Painted sashes

1920s window with horns in new
 opening. The stair windows to
 no. 34 appear to have been
 reconfigured. No panelling or
 other detail of interest.



W.01.88


NOTES :

Weighted sash
 6 panel sashes
 Painted sashes

1920s window with horns in new
 opening. The stair windows to
 no. 34 appear to have been
 reconfigured. No panelling or
 other detail of interest.

D.00.14

NOTES :



NOTES :

- Electrical wiring
- Concealed pipe route assumed

Rev	Date	Description	Author	Checker

Scale at A1 / A3
 1:25 / 1:50



Drawing Name
**Existing Internal Elevations
 Window Stack 10**