

W.03.14

NOTES :

Modern casement
Post condition
Manually operated blinds
3 panel sashes

1920s sash with horns. Historic
modest panel behind radiator
reflecting floor hierarchy.
Medium to high significance.




W.02.17

NOTES :

Weighted sash
6 panel sashes
OK condition
Manually operated blinds

INSPECTION REQUIRED



W.01.16

NOTES :

Weighted sash
Manually operated blinds shut

NOT POSSIBLE TO INSPECT



W.00.13

NOTES :


Weighted sash
6 panel mirrored sashes
OK condition

1920s with mirrored glazing.
Medium significance.



W.B1.11

NOTES :



--- Electrical wiring
- - - Concealed pipe route assumed

| Rev | Date | Description | Author | Checker |
|-----|------|-------------|--------|---------|
| | | | | |

Scale at A1 / A3
1:25 / 1:50



Drawing Name
**Existing Internal Elevations
Window Stack 17**

Drawing Number Revision
BW125 - BW - ## - XX - DR - E3017