

W.03.16

NOTES :

Modern casement
Post condition
Manually operated blinds

1920s sash with horns. Historic modest panel behind radiator reflecting floor hierarchy. Medium to high significance. Bay rebuilt 1926.



W.02.18

NOTES :

Weighted sash
6 panel sashes
Shutter box non functioning
Concealed radiator below
OK condition
Manually operated blinds

Rear bay rebuilt 1926 - 1926 windows and shutter boxes matching rear bay on other levels. Low to medium significance.



D.01.12

NOTES :

Doorway
Opening adapted for doorway to outrigger and fixed six light window to roof terrace
Timber framed


Window converted to a door by 1928. 1920s window over and modern window linings have replaced shutter boxes. Low to medium significance.




W.00.14

NOTES :

Window blocked 1926 because of rear extension. No shutters but instead simple linings with modest detailing. 1926 in date. Glazing bars of 1920s date. Mirrored glazing. Low to medium significance.



NOTES :



Rev	Date	Description	Author	Checker
-----	------	-------------	--------	---------

Scale at A1 / A3

1:25 / 1:50



Drawing Name

Existing Internal Elevations
Window Stack 19

Drawing Number Revision
BW125 - BW - ## - XX - DR - E3019

