
26 NETHERHALL GARDENS NW3 5TL

IMAGES OF EXISTING RETAINING WALL IN GARDEN

01.03.2023



EXISTING RETAINING WALL - NORTH



Image is of the left side of the existing retaining wall within the rear garden (when standing in the garden facing the rear boundary)

EXISTING RETAINING WALL - CENTRE



Image is of the centre of the existing retaining wall within the rear garden

EXISTING RETAINING WALL – SOUTH



Image is of the right side of the existing retaining wall within the rear garden (when standing in the garden facing the rear boundary)